




© The State of Queensland (Department of Natural Resources and Mines) 2021. Based on Cadastral Data provided with the permission of the Department of Natural Resources and Mines. The information contained within this document is given without acceptance of responsibility for its accuracy. The Bundaberg Regional Council (and its officers, servants and agents), contract and agree to supply information only on that basis.

While every care is taken to ensure the accuracy of this data, the Department of Natural Resources and Mines and the Bundaberg Regional Council makes no representation or warranties about its accuracy, reliability, completeness or stability for any particular purpose and disclaims all responsibility and all liability (including without limitation, liability in negligence) for all expenses, losses, damages (including indirect or consequential damage) and costs which you might incur as a result of the data being inaccurate or incomplete in any way and for any reason.

BRC Plan No. ??????
Printed By: Theresa Koning Date: 16/11/2021

Hydrant Inspection Locations
Kensington Map 2 of 2
Scale 1:5,000 on A1 Sheet